

2 5/8" Pyrometers INSTALLATION INSTRUCTIONS

1. Disconnect the negative (-) battery cable.
2. Mount pyrometer to dash using the supplied bracket, washers, and nuts (see figure A).
3. Install light in back of gauge and connect wire to dash lighting circuit.
4. Connect pyrometer as shown (see figure B). Locate a 1 amp fused terminal on fuse panel to supply 12v power to the gauge.
5. Extra care must be taken to ensure that all wiring connections are shielded from water spray, and that they are secure and correct.
6. Reconnect the negative (-) battery cable.

Grayslake, Illinois • 847-548-5900 • 847-548-5903 Fax

