

Mechanical Gauges Applying Torque to Fittings

Part Numbers beginning with: DCM or DCMS

1. Do not over torque the fitting or mounting screws, this will void the warranty.
2. Use multiple wrenches to counter torque fittings so as not bend or damage the case. Bending/damaging the case makes the gauge inaccurate.

